## **PB21 / PB41**

## **Stainless Steel Exit Button**



PB21

## **Features**

- The sensor is dry contact,, please do not exceep 5amp/125VAC & 3amp/250VAC when connect with power.
- In normal open mode(NO), please connect C with sensor NO contact.
- In normal close mode(NC), please connect C with sensor NC contact.
- Dimension

PB21 : 100mm (L) x 35mm (W) x 28mm (D) PB41 : 120mm (L) x 76.2mm (W) x 26mm (D)



PB41









